

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

| Representatives Present During the Inspection: | | | |
|--|---|--|--|
| Company | Dennis Oakley Environmental Engineer | | |
| OGM | Steve Demczak Environmental Scientist III | | |
| Company | Chuck Semborski Environmental Supervisor | | |

Inspection Report

| Permit Number: | C0150018 | | |
|------------------|------------------------------|--|--|
| Inspection Type: | PARTIAL | | |
| Inspection Date: | Wednesday, February 25, 2004 | | |
| Start Date/Time: | 02/25/2004 10:00:00 AM | | |
| End Date/Time: | 02/25/2004 3:00:00 PM | | |
| Last Inspection: | Friday, January 30, 2004 | | |

Inspector: Steve Demczak, Environmental Scientist III

Weather: Snow Cover, Partly Sunny, 40's

InspectionID Report Number: 190

Accepted by: dhaddock 03/08/2004

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

| Current Acreages | | Mineral Ownership | Types of Operations |
|------------------|------------------------|-------------------|---------------------|
| 24,638.52 | Total Permitted | ✓ Federal | Underground |
| 95.80 | Total Disturbed | ✓ State | Surface |
| | Phase I | ☐ County | ☐ Loadout |
| | Phase II | ✓ Fee | Processing |
| | Phase III | ☐ Other | Reprocessing |

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

| Inspector's Signature: | Date | Friday, February 27, 2004 |
|------------------------|----------|---------------------------|
| | | |

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0150018
Inspection Type: PARTIAL

Inspection Date: Wednesday, February 25, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | | Evaluated | Not Applicable | Comment | Enforcement |
|-----|---|--------------|----------------|----------|-------------|
| 1. | Permits, Change, Transfer, Renewal, Sale | \checkmark | | ✓ | ✓ |
| 2. | Signs and Markers | | | | |
| 3. | Topsoil | | | | |
| 4.a | Hydrologic Balance: Diversions | ✓ | | ✓ | |
| 4.b | Hydrologic Balance: Sediment Ponds and Impoundments | | | | |
| 4.c | Hydrologic Balance: Other Sediment Control Measures | ✓ | | ✓ | |
| 4.d | Hydrologic Balance: Water Monitoring | | | | |
| 4.e | Hydrologic Balance: Effluent Limitations | | | | |
| 5. | Explosives | | | | |
| 6. | Disposal of Excess Spoil, Fills, Benches | | | | |
| 7. | Coal Mine Waste, Refuse Piles, Impoundments | ✓ | | ✓ | |
| 8. | Noncoal Waste | ✓ | | ✓ | |
| 9. | Protection of Fish, Wildlife and Related Environmental Issues | | | | |
| 10. | Slides and Other Damage | | | | |
| 11. | Contemporaneous Reclamation | | | | |
| 12. | Backfilling And Grading | | | | |
| 13. | Revegetation | | | | |
| 14. | Subsidence Control | | | | |
| 15. | Cessation of Operations | | | | |
| 16. | a Roads: Construction, Maintenance, Surfacing | | | | |
| 16. | b Roads: Drainage Controls | | | | |
| 17. | Other Transportation Facilities | | | | |
| 18. | Support Facilities, Utility Installations | | | | |
| 19. | AVS Check | | | | |
| 20. | Air Quality Permit | | | | |
| 21. | Bonding and Insurance | | | | |
| 22. | Other | | | | |

Permit Number: C0150018
Inspection Type: PARTIAL

Inspection Date: Wednesday, February 25, 2004 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The permittee was removing snow which contained some non-coal waste material from the Deer Creek Mine disturbed area and deposited the material outside the permit area. The snow and non-coal waste was deposited at the Huntington Power Plant's ash pile. A Notice of Violation (04-39-3-1) was written for conducting mining activities outside the permit area. The MRP states that snow can be placed at the waste rock site of the Deer Creek Mine. The abatement is: the permittee will remove the non-coal waste material from the snow piles at the Huntington Power Plant's ash pile. The snow will report to a total containment impoundment at the ash pile.

4.a Hydrologic Balance: Diversions

The diversions were functioning as designed. Water was flowing within the diversions and drop drains.

4.c Hydrologic Balance: Other Sediment Control Measures

Several dugout ponds were inspected and functioning as designed.

7. Coal Mine Waste, Refuse Piles, Impoundments

The waste rock site was inspected with no hazardous conditions noticed during the inspection.

8. Noncoal Waste

The mine site area was clear of non-coal waste material. The permittee has added plastic mesh above and in front of the containment area to reduce the possibility of the material leaving the containment. The plastic mesh in front of the containment area was not being used.